To Buchanan SWD.

Department of Natural Resources
INTRA-DEPARTMENT
MEMORANDUM

Green Bay
Station

Date October 6, 1970

Division of Environmental Protection

TO: Sam Lagow

FROM: Dennis C. Weisensel

SUBJECT: Lehrer Sanitary Service Solid Waste Disposal Site, Town of Buchanan, Outagamie County

A field investigation of the Lehr Sanitary Service solid waste disposal operation was made at 3:30 P.M. on October 2, 1970, by this writer.

The following conditions were noted at the portion of the site which receives waste from the City of Kaukauna:

1. Open burning of garbage, paper, wood and paper mill waste was being conducted.

2. Large amounts of windblown papers were scattered about the dumping site.

3. Some compacting of waste material was done, however, this material was not sufficiently covered with earth.

Mr. Lehrer was personally contacted and informed this writer that he did not start the fires. He informed this writer that local people dumping their solid waste start the fires.

DCW

Dennis C. Weisensel
Environmental Technician

DCW:sbm

NOTED:

____________________ ________
Date

00548

DEPARTMENT OF NATURAL RESOURCES
Solid Waste Disposal - Site Evaluation

Licensee Lehr operation License No. ______

Officials: (Mayor, Chairman, Pres.) ______

(Clerk) ______

Responsible Person ______ Phone ______

Location Outagamie (county) Buchanan (township) Sec 25 (¼sec., town, range)

Type of Operation Sanitary Landfill Population served ______

Distances to: surface water — nearest dwelling ______

groundwater — bedrock — S.T.H. —

OPERATION CHECK LIST	YES	NO	REMARKS
Screened from view	(✓)	( )	
Lockable gate at entrance	(✓)	( )	Send memo early next week
Regulatory signs posted	( )	(✓)	
All-weather approach road	(✓)	( )	
Nuisance free (odors, loose paper, etc.)	( )	(✓)	
Site fenced	(✓)	( )	
Operator on duty	(✓)	( )	Mr. Lehr.
Compaction and covering	( )	(✓)	not entirely
Equipment available	( )	(✓)	None evident
Putrescible material covered	( )	(✓)	
Rodent and insect control	( )	(?)	
Burning practiced	(✓)	( )	Several fires - Garbage wood paper mill waste
Fire hazard in area	( )	(✓)	
Hazardous material at site	( )	(✓)	
Site subject to flooding	( )	(✓)	
Local official contacted	(✓)	( )	
Permit required (60.72 Stats.)	(✓)	( )	

00547

Comments Cond. lic.

Date visited Oct 2, 70 Evaluation by [signature]